


- Thousands of test samples evaluated for vehicles and equipment used by Truck Service Providers indicate that over extended oil occurs 19.3% of the time
- Abnormal wear within the transmission occurs 19.1% of the time
- Although abnormal wear indications may seem relatively low in some categories like engine wear at 10.1%, it's important to remember that catastrophic results like engine failure could result in any of those cases

Truck Service Providers:* Fluid Problems Identified by OSA



Source: OSA Lube Trak (*Truck Service Provider data results of 13,726 samples; 90 day period ending April , 2012 .